Name: Date: Class:

## **Cushions and Capacitance Exit Ticket Key**

**<u>Matching Directions:</u>** Match each of the following parts of the capacitance sensor you built with its function:

1.	Tin	ı Foil:	B	Tool used to connect the capacitance sensor with the digital multimeter.					
2.	Wa	ax Paper:	c	b. Material that is the <i>conductor</i> and is used to "sense" when the sensor is pushed.					
3.	Alli	gator Clips:	A	c. Material that is the <i>insulator</i> and is used In between two conductors in the sensor.					
4.	Dig	gital Multimeter:	D	d. Tool used to measure and display the capacitance of the sensor.					
<u>Patterns Directions:</u> Answer the following questions about the relationship between capacitance as pressure:									
Th	e se	ensor you created does related to the pressur	· · · · · · · · · · · · · · · · · · ·	ure, but it does measure capacitance which is directly					
	If you sit on the sensor, you are pushing the pieces of tin foil closer and closer together. This increases								
	2.	As the sensor is pushed down, the number shown on a digital multimeter willincrease(increase or decrease).							
	3.	If you sit on this sensor, you are pushing the pieces of tin foil closer and closer together, increasing the capacitance, this means that the pressureincreases(increases or decreases).							





<u>Data Calculation Directions:</u> A small, light box and a large box were placed on a capacitance sensor in two separate experiments. Calculate the capacitance of each box and answer the questions:

Object	Initial Capacitance (nF)	Final Capacitance (nF)	Object's Capacitance (nF)	
Small Box	0.45 nF	0.88 nF	0.88 nF – 0.45 nF = 0.43 nF	
Large Box	0.40 nF	1.07 nF	1.07 nF – 0.40 nF = 0.67 nF	

1	Which box has the hic	her canacitance?	The Large Box
Ι.	VVIIICII DOX HAS LITE HIL	HEL Capacitatice:	THE Large DUX





<sup>2.</sup> If you wanted to select the object that would put the *least* pressure on a surface, which box would you choose and why? You should choose the Small Box because it has the lowest capacitance, indicating that it would also put the least pressure on a surface.